



HI 991300C • HI 991301C pH, Conductivity, TDS & Temperature Waterproof Meters

- Measure 4 parameters with 1 probe
- Waterproof
- Automatic Temperature Compensation
- Automatic Calibration
- Shockproof Rubber Boot Included



